


Subject: Correct Lube Oil Filter Cartridge for GM 1.4L & 1.8L engines

On various model GM vehicles with 1.4L & 1.8L engines, two different Cartridge Oil Filter housing designs are used. Some engines will be equipped with a housing manufactured by Hengst, and other engines with a UFI housing. The cartridge filter used for each housing is different and is not interchangeable. **Using the incorrect filter can result in engine damage.**

Below are pictures of the housings and the location identifying the manufacturer. Also note that the color of the OE housing cap is different for each housing.

** For verification of the GM vehicle models affected refer to the current catalog information.*



Engine and equipment manufacturer's warranties remain in effect when using FRAM filters.

For more information or purchase, please call Technical Services at 1-800-890-2075. FRAM Group is an ISO/TS16949 registered company. The information contained herein is intended to be used as an indication of performance and is not meant to be used as an exact specification. The information is based upon test data and is subject to test and material variability. Changes may occur based upon technology, process and material innovation as FRAM Group strives to attain the highest levels of performance and customer satisfaction. These changes may occur without notification.