

Date: February 15, 2016
To: FRAM[®] Heavy Duty Customers
From: FRAM[®] Heavy Duty
Subject: Fuel Filter Thread Ring Reconfiguration


Service Bulletin - 02-15-2016

Thread Ring Reconfiguration

As part of our ongoing efforts to improve our products, the internal thread ring and bottom end cap on a few spin-on fuel filters have been modified. Please see the chart below for specific part numbers.

Customers who are affected by this change will be able to continue to use their current plastic and metal bowls with the new filters.

This product change will be implemented as a running change.



CURRENT DESIGN		NEW DESIGN	
			
PRODUCTS AFFECTED			
PS7713	PS9263	PS9794	PS9707